PRODUCT ENGINEERING

PUBLISHED MONTHLY

McGRAW-HILL PUBLISHING COMPANY, INC. 330 West 42d Street, New York, N. Y.

▼

INDEX TO VOLUME 5

January to December, 1934

January 1-40
February 41-80
March 81-120
April 121-160
May 161-200
June 201-240
July 241-280
August 281-320
September 321-360
October 361-400
November 401-440
December 441-480

Aeronautics—Speed reducer for variable pitch propeller *46

Air Conditioning:

Friez humidistat and thermostat—product case history *220
Wicking for evaporating surfaces in Taylor humidifier *211
Alloys, corrosion resisting — correction. LaQue, Peterson 109

Aluminum:

Impact extrusion process for aluminum parts. H. H. Hall *341
Reflectors of aluminum 86
Streamlined, aluminum train *112
Anemometer *127

Appearance and Finishes:

Case histories in product design. T. J. Maloney, pt. 7 *13; pt. 8 *52; pt. 9 *95; pt. 10 *218
Four economical processes for the decorative finish. Fred Weindel, Jr. *142
Industrial arts exposition. Exhibition of machine art, Fashion group exhibit *122
Parkerized finishes and Bonderite 48
Rust-proofing processes. L. F. Hirsh. *135
Trademarks—their relation to the product. Otto Kuhler *128
Applied mechanics—Determining the critical speeds of shafting. W. C. Willard *221

Automobiles:

DeSoto, Airflow *8
Does bigger mean better? F. C. Hudson 110
Engineering behind the 1934 models.. *42
Ford's exhibit at Century of Progress. W. D. Teague *282
Front-wheel suspension for 1934 automobiles *6
German developments in auto bodies. *208
How General Motors finds out what the customer wants *21
New designs thrill the crowds (ed)... 41
What the customer buys. F. K. Lawler 228
Axle stress reduced by cutting groove in hub *114

Bathysphere for Beebe with fused quartz windows *326
Beam, dredge, forces on. R. V. Hopkins. *147
Beams, deflection of variously loaded (Ref. Bk. Sheets) E. Cowan *199

Bearings:

Anti-friction 415
Anti-friction bearing mountings for heavy duty spindle. F. A. Firnhaber. pt. 1 *24; pt. 2 *55
Ball bearing conveyor rollers *89
Bearing bronzes grouped according to fields of use. C. H. Leis (Ref. Bk. Sheet) 240
Bearings and bearing seals 416
Bronze bearing alloys. C. H. Leis.... *202
Chemical and physical properties of bronze bearing alloys. C. H. Leis (Ref. Bk. Sheet) 239
Comparative index of radial type ball bearings. R. C. Deal 267
Jewel bearings *100
Jewel bearings for minimum friction. *178
Jewel bearings in electrical instruments. Lenehan, Stott 267
Knife-edge bearings *286
Laminated plastics for bearings and spinning pots. H. M. Richardson.. *60
Laminated, sheet bronze and graphited bearings. C. H. Leis *263
Lubrication of bearings. C. H. Leis.. *303
Needle bearings and their applications. Herbert Chase *461
Possible causes for bearing failure. C. H. Leis *377
Roller bearings for rolling mill service. *210
Safe loads for journal bearings. Victor Tatarinoff *455
Sealer-in ball bearings *420
Single bearing mountings. Hermann Hill *183
Single bearing mountings—bearings for pulley. Harry Shaw *467
Sleeve-type bearings. C. H. Leis *338
Belts—V-belt drives for veneer drier..... *248
Bending allowances. F. L. Tuxbury..... *189
Bending rolls, wrapping type *8
Beveller of magnesium alloy *406
Bicycles of stainless steel *357
Blueprinting machine *357
Book reviews.....38, 77, 118, 158, 198, 238, 278, 318, 358, 438, 478
Boring, drilling and milling machine.... *328
Boring, precision, machine *422
Bottle making machine *422
Bottling machine *411
Bottling machine, milk *410
Brakes—Thrustor operated brakes on cable drum *366
Bronze, high strength 113
Buick car has front wheel suspension.... *6
Bushing, eccentric, for adjusting belt tension 86

Calipers with tungsten carbide tips..... *369
Camera, aerial *366
Camera from molded plastics *168
Cams for high speeds. C. N. Neklutin.. pt. 1 *250; pt. 2 *296; pt. 3 *333
Can sealing machine *416
Carburetor *417
Case histories in product design. T. J. Maloney.....pt. 7 *13; pt. 8 *52; pt. 9 *95; pt. 10 *218

Castings:

Copper die castings *336
Designing for die castings—Initialator. M. G. Demougeot *130
Higher die casting pressures 393
Internal stresses in die castings. M. G. Demougeot *387
Phosphor bronze and steel in aluminum die castings *405
Sales register and vending machine of stampings and die castings. L. H. Morin *372
Two problems in inserts—die cast frame. F. S. Stickney *466
Centrifuge for the laboratory *89
Century of Progress—Ford's exhibit. W. D. Teague *282
Chair and stand for optical examinations. *420
Champagne cooler *430
Check writer *123, *430
Circular segments, areas and chordal heights. M. G. Van Voorhis (Ref. Bk. Sheets) 39
Clock, modernistic *124

Clutches:

"Servo principle" applied to power clutch on cranes and excavators.. *211
Tensions in clutch bands. R. H. Lewis (Ref. Bk. Sheets) 359
Typical mechanisms for station clutches. Hermann Hill *82
Coca-Cola dispenser *125
Color illusions 335
Color uses 233

Compressors:

Motor driven, with full automatic protection 8
Refrigeration compressor 48
Sleeve-valve compressor *47
Cone, perforated. Hutchinson 388; Tshopp. *308
Cone or hopper, perforated. C. O. Sandstrom *387
Connecting rod design. Henry Bohn..... *149
Connecting-rod end. R. V. Hutchinson.... *266
Contact units of laminated metal. G. A. Ruehmling *98
Contacts and electromagnets for magnetic contactors. E. W. Seeger *181

Controls:

Controls improved 367
Electric automatic controls for lathe. *424
Trends in control devices 422
Conveyor with bakelite parts 329
Conveyor with long overhang..... *327
Copper, chrome-plated 312

Corrosion:

Materials used for resisting corrosion.. 412
Metals selected for corrosion resistance 406
Covers and flexible joints, hinges and pivots for. H. J. Martin..... pt. 1 *230; pt. 2 *270
Curve analysis. J. S. Carpenter *68
Customer preference *21, 90
Cylinders, volume for intersection. R. L. Turner *148

Decalcomanias for name plates *428

Design, Calculations and Examples:

Anti-friction bearing mountings for heavy duty spindles. F. A. Firnhaber .....pt. 1 *24; pt. 2 *55
Areas of circular segments. M. G. Van Voorhis..... 39
Cantilever spring design. R. L. Peek, Jr. (Ref. Bk. Sheets) *439, *479
Avoiding stress concentration by using less material. R. V. Baud.....*170
Barth gear factors. A. C. Rasmussen (Ref. Bk. Sheets) 160
Bearing bronzes grouped according to fields of use. C. H. Leis (Ref. Bk. Sheet) 240
Cams for high speeds. C. N. Neklutin pt. 1 *250; pt. 2 *296; pt. 3 *333
Causes of bearing failure. C. H. Leis.*377
Charts for obtaining spring dimensions directly. Frederick Franz *215
Chemical and physical properties of bronze bearing alloys. C. H. Leis (Ref. Bk. Sheets) 239
Chordal heights of circular segments. M. G. Van Voorhis (Ref. Bk. Sheets) 40
Curve analysis. J. S. Carpenter..... *68
Deflection of variously loaded beams. E. Cowan (Ref. Bk. Sheets) *199
Design of stampings—parts produced by swaging. J. K. Olsen *442
Economic selection of metal parts. L. H. Morin *372
Faulty electrical design? (ed) 81
Fillet profiles for constant stress. R. V. Baud *133
Hydraulic versus mechanical feed. A. L. DeLeeuw.....pt. 2 *10
Industrial designer. Walter Teague.. 468
Laminated plastics for bearings and spinning pots. H. M. Richardson.. *60
Learning rule and rote does not make a designer. G. F. Nordenholt....*344
Mating gears rotating in the same direction. W. A. Tuplin *108
Nomogram for circular arcs. M. G. Van Voorhis (Ref. Bk. Sheets) ... 79
Photo-elastic tests and strain measure-

*Illustrated

ments to determine stress concentration. Wahl & Beeuwkes..... *92
Scale springs *207
Shaft diameters for torsion and bending. E. Cowan (Ref. Bk. Sheets) 200
Shot weld stainless steel sections... *242, *293
Sleeve-type bearings. C. H. Leis..... *338
Spur gears of laminated plastics. H. M. Richardson *18
Streamlining the railroads. O. Kuhler *224
Tension and compression springs. C. P. Nachod (Ref. Bk. Sheets) 279
Total efficiency for drive trains. A. C. Rasmussen (Ref. Bk. Sheets) 159
Typical mechanisms for station clutches. Hermann Hill *82
Worm gear design. C. H. Grill..... pt. 1 *2; pt. 2 *62
Development procedure. L. J. Lunas..... *31
Dishwasher, electric—product case history. *95
Door bumper, plastic molded..... *246
Drafting instruments *357

Drawings:

Drafting shortcut. J. R. Heilman... *306
How should limits be shown? R. E. Holbrook 29
Indicating tolerances in drawings. Wickstrand, Schemm, Underwood, Brown, Hoey 70
Scales for drawings. David Fliegelman 306

Drills:

Drill, hand, of aluminum alloy.... *407
Drill head *421
Drilling machine *421
Hydraulic drill *289
Planetary drill speeder unit *88

Drives:

Chain drive provides long reciprocating motion for polishing knives. J. E. Fenno *388
Crank drives. J. E. Fenno *349
Electric motor drives 426
Engineering the unit motorized machine *22
High speed friction drive. G. N. Krouse *346
Hydraulic stoker drive *168
Modernized design for group drive (ed) 281
Unfair to the belt drive. J. R. Hopkins 109
Woodworking machinery — drives and controls *176
Drums, stainless steel 48

Dryers:

Dryer made of corrosion-resisting material 169
Rotary drum dryer *249
Veneer dryer has V-belt drive 248
Duplication machine *430

Editorials:

Apprenticeship needed 241
Dust off the old plans 81
Faulty electrical design? 81
How do you make your inquiry?.... 241
How does it look? 121
If it's cheaper to kill them, take a chance 361
Job for engineering societies to start.. 161
Quackery dies while art endures 121
School of experience is always in session 321
Support the move for a design division 201
They shot a forward pass that thrilled the spectators 41
Try dynamite 161
What 1933 has promised 1934 1
Will your products sell? 441
You can't plow under new ideas..... 401
You can't stop progress 201
Electromagnets and contacts for magnetic contactors. E. W. Seeger *181
Engineers and engineering—Managing the engineer. M. G. Demougeot 186

Engines:

Crankless diesel engine *166
Diesel engine with chrome-molybdenum steel rods *327
Modern diesel engine compared with one of cast iron and carbon steel. Robert Wosak *362
Opposed piston diesel engine *287
Vibration. L. D. Hagenbook..... *110
Welded alloy steel engine bed for streamlined train *209
Welded diesel cylinders 366
Escalator model *122
Exhibitions—Industrial Arts Exposition, Exhibition of machine art, Fashion group exhibit *122

Fan, General Electric—product case history *15
Feed, hydraulic vs. mechanical. A. L. DeLeeuw ..... pt. 2 *10
Fillet curves. A. G. Solakian 189
Fillet tables. W. F. Brecht..... *468
Finishes. See Appearances and finishes.
Flow meter *126
Fulcrum, knife-edge *286
Furniture ornaments. J. E. Hyler 28

Gage, draft *87
Gas burner *413

Gears:

Barth factors. Mickle 349
Barth factors for worm gears. Bland, Grill 229
Barth gear factors. A. C. Rasmussen (Ref. Bk. Sheets) 160
Chart for Barth gear factors. F. A. Mickle 269
Designing with laminated plastics. H. M. Richardson *18
Dynamic loads on gear teeth. A. C. Rasmussen 468
Electric gearing. R. H. Rogers..... *290
Form generator for gear teeth. A. C. Rasmussen *226
Free-tumbler gear trains for multiple speeds. C. E. Pearce *459
Improving gear ratios. J. A. Hall *49; pt. 2 *103
Involoid gear. F. W. Shaw *31
Involoid gears. R. V. Hutchinson..*108
Load-carrying ability of metal spur gears 223
Mating gears rotating in the same direction. W. A. Tuplin *108
Safety gear for axle generators..... *247
Short-center gear drives. C. W. Hinman *227
Total efficiency for drive trains. A. C. Rasmussen (Ref. Bk. Sheets) 159
Worm gear design. C. H. Grill.... pt. 1 *2; pt. 2 *62
Worm gear efficiency. C. H. Grill 148
Gibs and guides, design of. Adam Fredericks .....pt. 1 *16; pt. 2 *58
Grinder, tool, with preloaded bearings.... *48
Grinder, with electric and hydraulic drives. *328
Grindstone, motorized *86

Heater—Electric:

Controlled by photocells *246
Electric heater *434
For fuel oil *87
For weld stress reliever *367
Heating equipment design 114
Hinges and pivots for covers and flexible joints. H. J. Martin....pt. 1 *230; pt. 2 *270
Hoist, ball bearing chain *166
Humidistat and thermostat, Friez—product case history *220

Ice cube tray of stainless steel..... *208
Ignition coils for operating in water 249
Impact extrusion process for aluminum parts. H. H. Hall *341
Inkstand and calendar combination..... *127
Invention procedure. L. A. Trofimov.... *65

Iron:

Cast iron. J. M. Lessells 375
Why alloy cast irons are used 404
Why the elastic modulus of iron is not a constant. J. M. Lessells ...*453
Ironer *430
Ironer, Easy—product case history *219

Jewel bearings *100

Kunial alloys 272

Lathes:

Automatic *424
Electrically controlled *47
Veneer, with spiral gears *87
Lavatory unit *124
Lawnmower with rubber tired V-belt drive 328
Lenses—how to lay out optical systems. R. C. Hitchcock *450
Light, sodium. Elliott, Benford 227
Lights without glare. E. L. Elliott..... 347
Loader, portable *9
Lock bolts for indexing mechanisms. Adam Fredericks.....pt. 1 *150; pt. 2 *190
Locking devices. Adam Fredericks..... pt. 1 *310; pt. 2 *350; pt. 3 *390; pt. 4 *470

Locomotives:

Chain drive locomotive *9
Fireless locomotive has welded insulated tank *248
Streamlining the railroads. O. Kuhler..*224
Welded alloy steel engine bed.....*209

Lubrication:

Applications of lubrication 419
Bearing lubrication. C. H. Leis.....*303
Fan motor for refrigerator has grooves to cause circulation of lubricant. P. H. Trickey *146
Oil circulated by centrifugal action in coal burner. G. M. Peltz *186
Safety control for lubricating systems. *87
Magnesium alloy parts *300
Magnesium alloy superchargers. H. G. Townsend *347
Manifold, silencing *89

Materials:

Bronze bearing alloys. C. H. Leis....*202
Cast iron. J. M. Lessells 375
Cold drawn steel for special sections..*257
Contact materials. E. W. Seeger...*181
Diesel of alloys compared with one of cast iron and carbon steel. Robert Wosak *362
Engineering data for designing molded plastics. F. W. Warner..pt. 1 *138 pt. 2 *173
Laminated plastics for spur gears. H. M. Richardson *18
Laminated plastics for bearings and spinning pots. H. M. Richardson. *60
Laminated, sheet bronze and graphited bearings. C. H. Leis *263
Magnesium alloy parts *300
1934 Product Engineering survey.... *402
Rubber for impact and abrasion. F. L. Haushalter *212
Selecting alloy steels for high temperature service *384
66 causes of defects in finished steel parts. Berg & Rockwell 382
Wear resistance materials 409
Materials. See also metals.
Measuring devices for toolmakers *126

Mechanisms and Constructions:

Dynamic loads on gear teeth. A. C. Rasmussen 468
Engineering behind 1934 models of automobiles *42
Gibs and guides. Adam Fredericks... pt. 1 *16; pt. 2 *58
Hinges and pivots for covers and flexible joints. H. J. Martin..... pt. 1 *230; pt. 2 *270
Improving gear ratios. J. A. Hall. *49; pt. 2 *103
Lining pressure for known tensions in clutch bands. R. H. Lewis (Ref. Bk. Sheets) 359
Lock bolts for indexing mechanisms. Adam Fredericks..pt. 1 *150; pt. 2 *190
Locking devices. Adam Fredericks.. pt. 1 *310; pt. 2 *350; pt. 3 *390, pt. 4 *470
1934 Product Engineering survey....*402
One-piece electrical contact units of laminated metal. G. A. Ruehmling *98
Pull at tight end of clutch bands. R. H. Lewis (Ref. Bk. Sheets).... 360
Safe loads for journal bearings. Victor Tatarinoff *455
Types of construction 414
Types of resistance welds and how they are used. F. S. Stickney *162

Metals:

Contact units of laminated metal. G. A. Ruehmling *98
Diesel of alloys compared with one of cast iron and carbon steel. Robert Wosak *362
Metals selected for high stresses and impact 405
Tests to determine metals to withstand sub-zero temperatures 20
Where light metals are used 407
Microscope of bakelite *368

Milling Machines:

Developments in Brown & Sharpe drives and controls since 1902....*106
Planetary milling machine *46
Mimeograph with wooden cabinet..... *125
Modulus of a rectangle section. H. R. Lloyd *111
Motor generator for charging batteries....*288

Motors:

Electric gearing. R. H. Rogers.....*290
Electric motor drives and controls.... 421
External inertia, or WR^2 and how to calculate it. J. W. Harper.....*379
Fan motor for refrigerator has grooves to cause circulation of lubricant. P. H. Trickey *146
Give motor manufacturers a chance to recommend 144
High speed built-in spindle motor ...*167
Spindle motor *419
Trends in motor applications..... 421
Mountings, single bearing. Hermann Hill..*183
Multigraph machine *427

Name plates *429
New materials and parts....33, 74, 115, 154, 194, 234, 274.. 314, 354, 394, 435, 474
Noise analyses of transportation vehicles (chart) 332

*Illustrated

Oil burner, quiet—product case history.. *97
Optical light source. R. C. Hitchcock....*450

Paints and varnishes, adoptions of 432

Parts and Units:

Copper die castings *336
Developments in Brown & Sharpe milling machine since 1902 .....*106
Engineering the unit motorized machine *22
Give motor manufacturers a chance to recommend 144
How to lay out optical systems. R. C. Hitchcock .....*.450
Jewel bearings *100
Jewel bearings for minimum friction..*178
Laminated, sheet bronze and graphited bearings. C. H. Leis *263
Locking devices. Adam Fredericks, pt. 1 *310; pt. 2 *350; pt. 3 *390
Motor drives and controls for woodworking machinery *176
Needle bearings and their applications. Herbert Chase *461
Problems in designing for die castings—Initialator. M. G. Demougeot.*130
Rod braces. S. D. Pool *330
Single bearing mountings—bearings for pulley. Harry Shaw.....*467
Tolerances for bolt holes. Robert Pash.*254
Pasteurizing outfit *414
Photo-elastic test of stress check *392
Photo-elastic tests and strain measurements. Wahl & Beeuwkes *92
Photo-elasticity for the designer. G. B. Karelitz 29

Photo-electric Cells:

Temperature of electric heater controlled by photocells *246
Vacuum tube relay to detect glue in grooves *8
Pilot-light control. I. E. McCabe *386
Pin and shaft design. H. F. Bariffi.....*187
Planer, woodworking *176

Plastics:

Designing with laminated plastics. H. M. Richardson *18
Engineering data for designing molded plastics. F. W. Warner..... pt. 1 *138; pt. 2 *173
Filing cabinet of Textolite 289
Fire alarm device of Bakelite.....*289
Laminated plastic sheets with printing *429
Laminated plastics for bearings and spinning pots. H. M. Richardson.. *60
Molded door bumper design.....*246
Plaskon parts for hardware *428
Plating and finishes 434
Plywood. J. E. Hyler 187
Polarimeter *126
Power factor, correcting. L. A. Corwin 469

Presses:

Press *419
Heavy duty press *422
Self contained high speed press *88
Product development chart. J. A. Honegger *307
Product Engineering—historical summary 1
Product Engineering Survey for 1934....*402

Pumps:

Chemical pumps *415
Gasoline pump *417
Pumps having nitralloy parts *408
Triplex *412
Wayne gasoline pump—product case history *13

Quartz, fused, windows for Beebe's bathysphere *326
Questionnaire for customers to discover preference—executives' comments .. 90

Radio, Philco *432
Range, gas *431, *433

Reference Book Sheets:

Areas of circular segments. M. G. Van Voorhis 39
Barth gear factors. A. C. Rasmussen.. 160
Bearing bronzes grouped according to fields of use. C. H. Leis 240
Cantilever spring design. R. L. Peek, Jr. 439, *479
Chemical and physical properties of bronze bearing alloys. C. H. Leis 239
Chordal heights of circular segments. M. G. Van Voorhis 40
Deflection of variously loaded beams. E. Cowan *199
Lining pressure for known tensions in clutch bands. R. H. Lewis 359
Nomogram for circular arcs. M. G. Van Voorhis 79
Pull at tight end of clutch bands. R. H. Lewis *360
Shaft diameter for lateral deflection. A. D. McKenzie 119, 120
Shaft diameters for torsion and bending. E. Cowan 200
Tension and compression springs. C. P. Nachod 279
Total efficiency for drive trains. A. C. Rasmussen 159
Volumes in horizontal round tanks. M. G. Van Voorhis 319
Volumes in vertical round tanks. M. G. Van Voorhis 320
Reflectors—how to lay out optical systems. R. C. Hitchcock *450
Reflectors of aluminum 86

Refrigeration and Refrigerators:

Chest type *369
Flat top *124
1934 Kelvinator refrigerator—product case history *218
Refrigeration of truck by its fuel....*286

Research and Development:

General Motors methods for discovering customer preference—comments by executives 90
How General Motors finds out what the customer wants *21
Instruments and methods of a machine tool research laboratory. Ernst & Martellotti *322, *370
Invention procedure. L. A. Trofimov. *65
Rheostat and gear reducer *423
Riveter partly of aluminum 329
Rod braces. S. D. Pool *330

Rubber:

Resistant to impact and abrasion. F. L. Haushalter *212
Synthetic rubber tested 312
Rust-proofing processes. L. F. Hirsh....*135

Sales register redesigned. L. H. Morin..*372
Sand-blasting barrel *288
Saw-band—product case history *54
Scale for Holley Carburetor *122
Screw threads, intensity of stresses in. H. F. Moore *307
Section modulus at an angle. Lloyd, Van Voorhis *69
Server, buffet *431
Settee, modern *431

Shafts:

Shaft diameters for torsion and bending. E. Cowan (Ref. Bk. Sheets) 200
Shaft diaemter for torsional deflection and lateral deflection. A. D. McKenzie (Ref. Bk. Sheets) 119
lard *221
Speed of horizontal shaft. W. C. Wil-
Shift, hydraulic, for change gears.....*167
Shovel of nickel-manganese steel castings *404
Slicer, bread *411
Slicewrapper of magnesium alloy *407
Snap ring design. R. V. Hutchinson....*188
Sodium lamps 113
Speed reducer, three stage *169
Speed reducer for variable pitch propeller.. *46
Spindle pots made of laminated plastics. H. M. Richardson *60
Spindles—Anti friction bearing mountings for heavy duty spindles. F. A. Firnhaber.....pt. 1 *24; pt. 2 *55

Springs:

Cantilever spring design. R. L. Peek, Jr. (Ref. Bk. Sheet).....439, *479
Charts for obtaining spring dimensions directly. Frederick Franz *215
Comparing spring charts. C. P. Nachod 309
Heavy coil spring *126
Helical springs. Franz, Nachod *347
Mechanical springs of stainless steel. J. K. Wood 349
Scale springs *207
Stresses in a large spring. Nachod. Smith *389
Tension and compression springs. C. P. Nachod (Ref. Bk. Sheets) 279

Stampings:

Design of stampings—parts produced by swaging. J. K. Olsen.....*442
Sales register and vending machine of stampings and die castings. L. H. Morin *372
Stampings for economy 413
Standardization—New standards for steel.. 273

Steel:

Alloy steels for various requirements 404
Cold drawn steel for special sections..*257
European applications of alloy steels. 113
Grain size in steel. Howard Scott..*468
Selecting alloy steels for high temperature service *384
Shot-welded stainless steel sections... *242, *293
66 causes of defects in finished steel parts. Berg & Rockwell 382
Tolerances in cold drawn sections. C. H. Wilson *349
Stellite facings *409
Sterilizer design. W. B. Underwood..... 70
Stoker with five speed transmission.....*249
Stove of porcelain enamel *434

Stresses:

Analysis of stresses in connecting rod. A. G. Solakian 308
Avoiding stress concentration by using less material. R. V. Baud *170
Connecting rods stresses. R. J. Palmer 347
Fillet profiles for constant stress. R. V. Baud *133
Intensity of stresses in standard threads. H. F. Moore *307
Internal stresses in die castings. M. G. Demougeot *387
Large spring stresses. Nachod. Smith..*389
Snap ring stresses. W. Schroeder...*228
Stress concentration produced by holes and notches. Wahl & Beeuwkes ... *92
Thread stresses. G. B. Karelitz *389
Swaging, parts produced by. J. K. Olsen.*442

Tanks:

Volumes in horizontal round tanks. M. G. Van Voorhis (Ref. Bk. Sheet) 319
Volumes in vertical round tanks. M. G. Van Voorhis (Ref. Bk. Sheet) 320
Taper pin chart. M. G. Demougeot *308
Tapping machine *423
Tenoning machine *177
Testing structures by comparison of sound waves. E. J. Tangerman 29
Textile machinery trends 368
Thermostat for gas range *433
Timer measures split seconds 112
Tolerances for bolt holes. Robert Pash..*254
Trademarks. Otto Kuhler *128

Trains—Streamlined:

Aluminum streamlined *112
Stainless-steel, streamlined 312
Streamline, uses Cor-Ten steel *408
Streamlined—Zephyr *192
Streamlining the train. O. Kuhler....*224
Transmission, variable speed. H. A. Nelson *28
Triangle problem. Hinman....*71; Snyder, Harris, Bariffin, Johnson, Macy *30

Trucks:

Automatic *405
Electric industrial, has compensating wheels *247
Street railway *426
Truck refrigerated by its fuel.....*286
Two wheeled, with tungsten coated legs 369
Tubing, parts for seamless steel. R. V. Hutchinson 148
Typewriter, Royal *427

Vacuum cleaner, Apex—product case history *14

Valves:

Float valve *416
Hardened stainless steel for valves.. 366
Pressure operated valves for gas furnaces *209
Solenoid valve 289
Vending machine for bottled "Coca-Cola." L. H. Morin *372
Vibrating table with wobble motion. J. E. Fenno *266
Vibration damping and noise elimination.. 429
Vibrator, portable, for concrete *368
Volume for intersecting cylinders. Manious Gottlieb *189

Washing machine for vegetables *287
Watch for hand-bag—product case history *53
Water-cooler, electric—product case history *52

Welding:

Coated electrodes for high quality welds 232
Fireless locomotive has welded insulated tank *248
Internal stresses in welds 206
Resistance welder *418
Shot welded stainless steel sections.. *242, *293
Spheres for joining tubes. Burstall, Smith, Kenney *261
Spot welding reduces scrap. F. S. Stickney *308
Types of resistance welds and how they are used. F. S. Stickney *162
Wheel, mine car *422
Wheel, printing, die cast *387
Wobble motion for vibrator. J. E. Fenno.*266
WR^2 or external inertia and how to calculate it. J. W. Harper *379
Wrench, foolproof chuck *168

*Illustrated

AUTHORS

BANTON, E. H. Drafting room efficiency. 188

Barber, A. H. Questionnaire not for dairy equipment manufacturers 149
Bariffi, H. F. Design formula for a pin and shaft of equal strength.... 187
Triangle problem ..... •30
Barr, J. M. Calculus not a memory stunt. 187
Baud, R. V. Avoiding stress concentration by using less material .....•170
Fillet profiles for constant stress....•133
Beeuwkes, R., and A. M. Wahl. Stress concentration produced by holes and notches ..... •92
Benford, Frank. Sodium light 228
Berg, Werner H. C., and S. P. Rockwell. 66 causes of defects in finished steel parts 382
Bland, P. N. Barth factors for worm gears 229
Block, E. Tables wanted 468
Bohn, Henry. Design of a connecting rod.•149
Bower, T. J. Shear pins 229
Bowers, Henry S. Is calculus necessary?.. 69
Brecht, W. F. Fillet tables .....•468
Brown, W. S. Showing drawing limits.... 71
Bryant, P. H. Mental perspective in problem analysis 268
Burstall, A. F., R. A. Smith and H. Kenney. Spheres for joining tubes..•261

CARPENTER, JOHN S. Determinants simplify curve analysis ..... •68
Plotting curves 387
Time saving triangle ..... •31
Chase, Herbert. Needle bearings and their applications .....•461
Cohen, Harry E. Improved style or performance 111
Corwin, L. A. Correcting power factor.. 469
Cossaboon, Karl. Forces on a dredge bucket beam ..... •71
Cowan, E. Deflection of variously loaded beams (Ref. Bk. Sheets) .....•199
Shaft diameters for torsion and bending (Ref. Bk. Sheets) 200

DEALE, ROBERT COREY. Comparative index of radial type ball bearings 267
Protection of ideas 69
DeLeuw, A. L. Hydraulic versus mechanical feed .....pt. 2 •10
Demougeot, M. G. Efficiency of draftsmen. 228
Internal stresses in die castings.....•387
Managing the engineer 186
Market investigation by questionnaire 268
Problems in designing for die castings .....•130
Taper pin chart .....•308
Dunn, J. S. Evolution of business..... 467

ELLIOTT, E. L. Light without glare.. 347
Visual properties of sodium light.. 227
Ernst, Hans, and Mario Martellotti. Instruments and methods for research .....•322, •370

FENNO, J. E. Crank drives.....•349
Long reciprocating movement .....•388
Wobble motion for vibrator .....•266
Firnhaber, F. A. Anti-friction bearing mountings for heavy duty spindles pt. 1 •24; pt. 2 •55
Fliegelman, David. Scales for drawings.. 306
Franz, Frederick. Charts for obtaining spring dimensions directly .....•215
Why avoid large Wahl factors? 347
Fredericks, Adam. Eight types of retaining and locking devices.....
pt. 1 •310; pt. 2 •350; pt. 3 •390, pt. 4 •470
Typical designs of gibs and guides..
pt. 1 •16; pt. 2 •58
Typical designs of lock bolts for indexing mechanisms..pt. 1 •150; pt. 2 •190

GOTTLIEB, MANIOUS. Volume for intersecting cylinders .....•189
Grill, C. H. Barth factors for worm gears 229
Practical data and formulas for the design of worm gears.pt. 1 •2; pt. 2 •62
Worm gear efficiency 147

HAGENBOOK, L. D. Engine vibration.. 110
Hall, Herbert H. Designs that can be made by impact extrusion .....•341
Hall, James A. Design papers wanted . 467
Gear trains for changeable speed ratios. 49; pt. 2 .....•103
Harper, John W. Significance of WR^2 and how to calculate it .....•379
Harris, Norman C. Triangle problem.... •30
Hatchel, E. P. Snap ring design wanted. •70
Haushalter, F. L. Rubber for impact and abrasion .....•212
Heilman, J. R. Drafting shortcut .....•306
Hill, Hermann. Avoiding common defects in single bearing mountings....•188
Typical mechanisms for station clutches •82
Hinman, C. W. Short center gear drives..•227
Triangle problem .....•71
Hirsh, Leonard F. Surface protection.....•135
Hitchcock, R. C. How to lay out optical systems .....•450
Hoey, G. Charles. Showing drawing limits 71
Holbrook, R. E. How should limits be shown? 29
Honegger, John A. Developing a product.•307
Hopkins, J. R. Unfair to the belt drive.. 109
Hopkins, R. V. Forces on a dredge beam..•147
Hudson, Frank C. Does bigger mean better? 110
New problems in engine design..... 306
Hutchinson, Roland V. Design of connecting rod end .....•266
Design of perforated filter cone..... 389
Other involoid gears .....•108
Parts from seamless steel tubing.... 148
Snap ring design .....•188
Hyler, John E. Furniture ornaments.... 28
Using a mirror in design 147
Wood shrinkage 187

JOHNSON, WILLIAM. Triangle problem. •30

KARELITZ, G. B. Photo-elasticity for the designer 29
Stresses in threads .....•389
Kenney, Harold, A. F. Burstall and R. A. Smith. Spheres for joining tubes.•261
Krouse, G. N. High speed friction drive.•346
Kuhler, O. Streamlining the railroads....•224
Trademarks—their relation to the product .....•128

LA QUE, F. L. Corrosion resisting alloys —correction 109
Lawler, F. K. What the customer buys.. 228
Leis, C. H. Bearing bronzes grouped according to fields of use (Ref. Bk. Sheet) 240
Bronze bearing alloys .....•202
Chemical and physical properties of bronze bearing alloys (Ref. Bk. Sheet) 239
Fundamental requirements for bearing lubrication .....•303
Laminated, sheet bronze and graphited bearings .....•263
Possible causes for bearing failure..•377
Sleeve-type bearings—design and protection .....•338
Lenehan, B. E. Jewel bearings in electrical instruments 267
Lessells, J. M. Cast iron—the dean of ferrous metals 375
Why the elastic modulus of iron is not a constant .....•453
Lewis, R. H. Lining pressure for known tensions in clutch bands (Ref. Bk. Sheets) 359
Pull at tight end of clutch bands (Ref. Bk. Sheets) 360
Lloyd, H. R. Criticism of chart for modulus of a rectangle section..•111
Section modulus at an angle ..... •69
Lunas, L. J. Development procedure.... 31

MACY, C. D. Triangle problem..... •31
Maloney, T. J. Case histories in product design.....pt. 7 •13; pt. 8 •52; pt. 9 •95; pt. 10 •218
Martellotti, Mario, and Hans Ernst. Instruments and methods for research .....•322, •370
Martin, Henry J. Hinges and pivots for covers and flexible joints.....
pt. 1 •230; pt. 2 •270
McCabe, I. E. Pilot light control.....•386
McKenzie, A. D. Shaft diameter for lateral deflection (Ref. Bk. Sheets) ... 120
Shaft diameter for torsional deflection (Ref. Bk. Sheets) 119
Mickle, Frank A. Chart for Barth gear factors 269
Charts for Barth factors 349
Moore, H. F. Intensity of stresses in standard threads .....•307
Morin, Louis H. Economic selection of metal parts in product design....•372

NACHOD, CARL P. Comparing spring charts 309
Stresses in a large spring 389
Tension and compression springs (Ref. Bk. Sheets) 279
Why avoid large Wahl factors?.....•348
Neklutin, C. N. Cams for high speeds..
pt. 1 •250; pt. 2 •296; pt. 3 •333
Nelson, H. Anthony. Variable speed transmission ..... •28
Nordenholdt, G. F. Learning rule and rote does not make a designer .....•344
North, C. U. Error in worm gear formula 109

OLSEN, J. K. Design of stampings....•442

PALMER, R. J. Stresses in connecting rods 347
Tolerances 309
Pash, Robert. Clearance hole toleranes for interchangeability .....•254
Pearce, C. E. Free-tumbler gear trains for multiple speeds .....•459
Peek, R. L., Jr. Cantilever spring design (Ref. Bk. Sheet) .....439, •479
Peltz, G. M. Oil circulated by centrifugal action .....•186
Peterson, A. W. Corrosion resisting alloys —correction 109
Pool, Stuart D. Design of end connections for round rod braces .....•330

RAH, JOSEPH C. Using consultants.... 386
Rasmussen, A. C. Accuracy of charts.... 309
Barth gear factors (Ref. Bk. Sheets) 160
Dynamic loads on gear teeth 468
Form generator for gear teeth.....•226
Total efficiency for drive trains (Ref. Bk. Sheets) 159
Richardson, H. M. Designing with laminated plastics .....•18
Laminated plastics for bearings and spinning pots .....•60
Rockwell, Stanley P., and W. H. C. Berg. 66 causes of defects in finished steel parts 382
Rogers, R. H. Electric gearing to avoid mechanical complications .....•290
Ruehmling, George A. One piece electrical contact units of laminated metal •98

SANDSTROM, C. O. Perforated cone design .....•387
Schemm, Hans. Showing drawing limits... 71
Schroeder, Walter. Stresses in a snap ring.•228
Scott, Howard. Grain size in steel.....•468
Seeger, E. W. Electromagnets and contacts for magnetic contactors....•181
Shaw, Francis W. Involoid gear..... 31
Shaw, Harry. Single bearing mountings..•467
Shuster, J. R. Efficiency of draftsmen.... 146
Smith, DuRay. Stresses in a large spring.•389
Smith, R. A., A. F. Burstall and H. Kenney. Spheres for joining tubes .....•261
Snyder, Sylvester S. Triangle problem.... •30
Solakian, A. G. Analysis of stresses in connecting rod 308
Spiral curves for fillets 189
Stickney, F. S. Spot welding reduces scrap.•308
Two problems in inserts .....•466
Types of resistance welds and how they are used .....•162
Stott, V. Jewel bearings in electrical instruments 268

TANGERMAN, E. J. Sonic non-destructive testing 29
Tatarinoff, Victor. Safe loads for journal bearings .....•455
Taylor, H. E. Practical professors needed 388
Teague, Walter Dorwin. Designing Ford's exhibit at Century of Progress..•282
Industrial designer 468
Townsend, H. G. Magnesium alloy superchargers .....•347
Trickey, P. H. Lubricant circulated without a pump .....•146
Trofimov, Lev A. Producing and sifting ideas .....•65
Tschopp, E. A. Design of perforated cone.•308
Tuplin, W. A. Mating gears rotating in the same direction .....•108
Turner, R. L. Volume for intersecting cylinders .....•148
Tuxbury, F. L. Bending allowances....•189

UNDERWOOD, C. A. Showing drawing limits 71
Underwood, W. B. Sterilizer design.... 70

VAN VOORHIS, M. G. Areas of circular segments (Ref. Bk. Sheets).... 39
Chordal heights of circular segments (Ref. Bk. Sheets) 40
Nomogram for circular arcs (Ref. Bk. Sheets) 79
Section modulus at an angle ..... •69
Volumes in horizontal round tanks (Ref. Bk. Sheet) 319
Volumes in vertical round tanks (Ref. Bk. Sheet) 320

WAHL, A. M., and R. Beeuwkes. Stress concentration produced by holes and notches ..... •92
Warner, F. W. Engineering data for designing molded plastics .....
pt. 1 •138; pt. 2 •173
Weibel, E. E. Fillet profiles..... 268
Weindel, Fred Jr. Four economical processes for the decorative finish .....•142
Wickstrand, Norman M. Pin and shaft of equal strength 268
Showing drawing limits 70
Willard, William C. Determining the critical speeds of shafting.....•221
Wilson, C. H. Tolerances in cold drawn sections .....•349
Wood, Joseph K. Mechanical springs of stainless steel 349
Wosak, Robert. Saving money by using costly metals .....•362
Wynn, Harold L. Drafting shortcuts....•111
Drawing and pattern symbols..... 469

•Illustrated